



AQ Matic Valve & Controls Company, Inc.

Entry Level CNC Machine Operator

Experience is not necessary although helpful in the production operations of various types of CNC and Manual Equipment to include but not limited to CNC Vertical and CNC lathes machines. Hiring criteria will be based on mechanical ability and experience level.

General Duties:

- Work with various type of hard gages for the inspection of parts being produced.
 - Thread Ring Gages, Thread Plug Gages and Plug Gages
- Ability to learn various type of additional inspection equipment to include but not limited to Caliper's and Micrometers
- Ability to interpret work instruction
- Deburr and Clean Parts
- Examine, or test completed parts to check for defects and ensure conformance to specifications, using inspection instruments and visual inspection
- Ability to lift manipulate objects up to 50 lbs
- It is essential for the applicant to be detail oriented and able to ensure quality of produced items