



AQ Matic Valve & Controls Company, Inc.

---

## **Experienced CNC Machine Operator**

Experienced CNC Operators needed. Must have 1 to 2 years experience in the operations of CNC and Manual machines. Equipment includes but not limited to CNC Vertical and CNC Lathe Machines. Hiring criteria will be based on experience level and the ability to do set-ups or help perform them.

### **General Duties:**

- Read blueprints
- Have working knowledge of materials
- Machine parts to specifications
- Inspect parts with various measure equipment ( hard and variable gages)
- Ability to make machine offsets
- Change cutting tools when necessary
- Deburr and Clean Parts
- Examine, or test completed parts to check for defects and ensure conformance to specifications.
- Ability to lift manipulate objects up to 50 lbs
- It is essential for the applicant to be detail oriented and able to ensure quality of produced items